

Removing Lead in Soil from Lead-Based Paint around Gazebo in Farragut Park



Removing Transformer Pad and Contaminated Soils at Former Transformer Location east of Building 459




Removing Contaminated Concrete at Transformer Pad

Documents in Review	Upcoming Documents	Milestones
Land Use Covenants for PCB Sites in IA D1.2	Draft Removal Action Work Plan for IR21 in IA C2	Eleven PCB Sites Closed
	Draft Remedial Action Plan for IA B	
Land Use Covenant Implementation and Enforcement Plan for IA H2	Land Use Covenant and Implementation Plan for IA D1.2	
	Interim Removal Action Work Plan for Industrial Wastewater Pump Station No. 4	

New Issues of Concern	Upcoming Public Comment Periods	Environmental Site Closure Status
None	Public Comment Period for IA C3 Remedial Action Plan, (On hold pending additional characterization work in IA C3)	358 of 570 PCB Sites Closed by DTSC and EPA 63 of 112 UST Sites Closed by RWQCB 55 of 111 FOPL Segments Closed by RWQCB

- LEGEND**
- PCB SITES
 - IWPS PUMP STATIONS
 - INVESTIGATION AREA
 - FUEL OIL PIPELINE
 - INDUSTRIAL WASTEWATER PIPELINE (IR14)
 - ROADS
 - STRUCTURES
 - WATER
 - WETLANDS
 - EETP
- FOUR KEY STAGES OF CLEANUP**
- SURVEY & SAMPLING
 - REMEDIAL INVESTIGATION / FEASIBILITY STUDY
 - REMEDIAL ACTION / CLEANUP
 - PENDING CLOSURE / CLOSED



FEATURES WITHIN THE EETP
 APRIL 2005 RAB UPDATE
 LENNAR MARE ISLAND, VALLEJO CALIFORNIA