

Floor removal in Building 680



Sawcutting FOPL Segment in Preparation for Vacuum Testing of the Pipeline



Floor removal in Building 680



Preparing to install groundwater monitoring wells

Documents in Review	Upcoming Documents	Milestones
Application for Risk Based Closure of PCB Sites Inside B728, B738, and B746 within IA C2	Crane Test Area Removal Action Work Plan, IA B	5 PCB Sites Closed by USEPA
Responses to Comments on the MI Work Plan for Additional Characterization at Sanitary Sewer Site, dated May 2004		
Cleanup Plan for Concrete and Asphalt at B516 and B516A PCB Sites within IA C3	Draft Remedial Investigation for IR14 in IA C2	UST OR-16 Closed by DTSC
Request for Closure of Previously-Unidentified UST 45 East, IA C2		
Land-use Covenant Implementation and Enforcement Plan for IA C3		
Site Characterization and Cleanup Action for PCBs at B521, IA D1.2		

New Issues of Concern	Upcoming Public Comment Periods
None	Public Comment Period for IA C3 RAP, May 2005 Interim Removal Action Work Plan for the Outdoor PCB Sites - December 2004


Environmental Site Closure Status
324 of 570 PCB Sites Closed by DTSC and EPA
63 of 112 UST Sites Closed by RWQCB
55 of 111 FOPL Segments Closed by RWQCB

LEGEND

- INVESTIGATION AREA
- SANITARY SEWER PIPELINE WITHIN IA's B, C1, AND C2
- FUEL OIL PIPELINE
- ROADS
- STRUCTURES
- WATER
- WETLANDS
- EETP

FOUR KEY STAGES OF CLEANUP

- SURVEY & SAMPLING
- REMEDIAL INVESTIGATION / FEASIBILITY STUDY
- REMEDIAL ACTION / CLEANUP
- PENDING CLOSURE / CLOSED



FEATURES WITHIN THE EETP
 DECEMBER 2004 RAB UPDATE
 LENNAR MARE ISLAND, VALLEJO CALIFORNIA