




Backfilling at UST 231 Area April 3, 2009



Backfilling and compacting pipe trench located between B1310 and B206 April 23, 2009



Soil Removal around Subsurface Utility and FOPLB290




LEGEND

- IWPS PUMP STATIONS
- UNDERGROUND STORAGE TANK SITES
- PCB SITES - 100% COMPLETE
- FUEL-OIL PIPELINE NEAR BUILDING 85 AND BUILDING 111
- INVESTIGATION AREA
- INVESTIGATION AREAS B.2-1 AND B.2-2
- EETP
- GROUP I SITES
- STRUCTURES
- ROADS
- WATER

FOUR KEY STAGES OF CLEANUP

- SURVEY & SAMPLING
- REMEDIAL INVESTIGATION / FEASIBILITY STUDY
- REMEDIAL ACTION / CLEANUP
- PENDING CLOSURE / CLOSED
- WETLANDS



FEATURES WITHIN THE EETP
 APRIL 2009 RAB UPDATE
 LENNAR MARE ISLAND, VALLEJO, CALIFORNIA

Documents in Review	Significant Upcoming Documents	New Issues
IA B.1 FS/RAP (DTSC)	Draft IR15 FS/RAP (IA C1)	None
IA B.1 CEQA Initial Study (DTSC)		
IA C2 CEQA Initial Study (DTSC)		
Upcoming Public Comment Periods	Environmental Site Closure Status	Milestones
IA B.1 FS/RAP (Crane Test Area)	450 of 570 PCB Sites Closed by DTSC and EPA	None
IA C3 FS/RAP for Black Granular Material in the Triangle Area	91 of 113 UST Sites Closed by RWQCB	
IA C2 FS/RAW for IR21	68 of 111 FOPL Segments Closed by RWQCB	