




Pouring Slurry Backfill in Shallow Bays



Removing Periscope Towers inside Building 680




Installing Shallow Storm Water Pipeline

LEGEND

- IWPS PUMP STATIONS
- UNDERGROUND STORAGE TANK SITES
- PCB SITES
- INVESTIGATION AREA
- INVESTIGATION AREAS B.2-1
- EETP
- GROUP I SITES
- STRUCTURES
- ROADS
- WATER
- WETLANDS

FOUR KEY STAGES OF CLEANUP

- SURVEY & SAMPLING
- REMEDIAL INVESTIGATION / FEASIBILITY STUDY
- REMEDIAL ACTION / CLEANUP
- PENDING CLOSURE / CLOSED



FEATURES WITHIN THE EETP
 JANUARY 2010 RAB UPDATE
 LENNAR MARE ISLAND, VALLEJO, CALIFORNIA

Documents in Review	Significant Upcoming Documents	New Issues
Draft IA B.2-1 Implementation Report	Final IA B.1 FS/RAP	None
Draft Final IA C2 RAP (Water Board)	IA B.1 Remedial Design Workplan	
Draft IA C1 RAP		

Upcoming Public Comment Periods	Environmental Site Closure Status	Milestones
	477 of 570 PCB Sites Closed by DTSC and EPA	None
	95 of 113 UST Sites Closed by Water Board	
	85 of 111 FOPL Segments Closed by Water Board	