



Duplicate QA/QC soil gas sample being collected in Summa for fixed lab analysis



Sample purging syringe and extraction vacuum gauge being used before collection of primary sample

Submitted Documents:
LUC Operations and Maintenance Plan for the EETP
Final IA B.2-1 Land Use Covenant
Revised Final IA C3 Triangle BGM Implementation Report
Response to Comments - Building 121 UL#04 PCB Site Where No Further Action is Required Request
Final Groundwater Monitoring Plan for IWPS No. 4 and Oil/Water Separator T-2
IR15 Groundwater Monitoring Report, Baseline and First Quarter 2011
Building 69 UL#02 and UL#03 PCB Sites Cleanup Plan and Notification
Building 746 UL#01 PCB Site Cleanup Plan
Building 854 UL#01 PCB Site Cleanup Plan and Notification
Building 1304 UL#01 PCB Site Cleanup Plan and Notification
Building 1342 UL#01 PCB Site Where No Further Action is Required Request
Implementation Report for Investigation of ABM Near former Building 531




Building 69 PCB Sites UL#02 and UL#03 Floor Grid Sampling

LEGEND

- INVESTIGATION AREA
- IA C3 TRIANGLE AREA
- EETP
- GROUP I SITES
- STRUCTURES
- ROADS
- WATER
- WETLANDS

FOUR KEY STAGES OF CLEANUP

- SURVEY & SAMPLING
- REMEDIAL INVESTIGATION / FEASIBILITY STUDY
- REMEDIAL ACTION / CLEANUP
- PENDING CLOSURE / CLOSED



FEATURES WITHIN THE EETP
 JUNE 2011 RAB UPDATE
 LENNAR MARE ISLAND, VALLEJO, CALIFORNIA