

Overexcavation at FOPL H1.6.B85.EX02



Monitoring Well Installation Inside Building 225



Closeup of Limited Access Sonic Drill Rig



Trenching along FOPL Segment on South Side of B121

LEGEND

- UNDERGROUND STORAGE TANK SITES
- PCB SITES
- INDUSTRIAL WASTEWATER PIPELINE (IR14)
- FUEL-OIL PIPELINE IN BUILDING 85
- - - INVESTIGATION AREA
- INVESTIGATION AREA B.2
- EETP
- GROUP I SITES
- STRUCTURES
- ROADS
- WATER

FOUR KEY STAGES OF CLEANUP

- SURVEY & SAMPLING
- REMEDIAL INVESTIGATION / FEASIBILITY STUDY
- REMEDIAL ACTION / CLEANUP
- PENDING CLOSURE / CLOSED
- WETLANDS

0 1,200 Feet

Documents in Review	Significant Upcoming Documents	New Issues
Feasibility Study/Remedial Action Work Plan for the B461 Area (DTSC and Water Board)	IR21 FS/RAP (DTSC and Water Board)	None
Addendum to the Draft UST Removal Work Plan for UST Site 102 (DTSC)	FS/RAW for Black Granular Material at B108/IR09/IR12 in C3 (DTSC and Water Board)	
IA C3 Implementation Report Addendum for Former IR09 Tanks 334-1 through 334-4 (DTSC and Water Board)	IR15 FS/RAP (DTSC and Water Board)	
IA C2 FOPL Work Plan (DTSC and Water Board)		
Upcoming Public Comment Periods	Environmental Site Closure Status	Milestones
Building 461 Remedial Action Work Plan	442 of 570 PCB Sites Closed by DTSC and EPA 80 of 112 UST Sites Closed by RWQCB	None
IA B.1 Crane Test Area Remedial Action Plan	61 of 111 FOPL Segments Closed by RWQCB	

FEATURES WITHIN THE EETP
 OCTOBER 2008 RAB UPDATE
 LENNAR MARE ISLAND, VALLEJO, CALIFORNIA